DAF	RT AERO	SPACE LTD		Work Order :	22	1(4
				Description:	Inspection	
				Approval :		
	W 1 20 2 2 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2			Арргочаг :		
		110			Pag	e 1 of 1
Step	Location	Procedure			Ву	Date
	PK 	Remove from Stock Yes Recurn# 314 Qty Part Number 1 02665-1 1 02666-1 1 02666-2	Description Security	Batch 1320214- 1320215- 1520216 1620217-	B	4.12.10
	FP Qc3 -ST	Re-work/Inspection: Touchup 93 pa Inspect level Deturn to 5to	25 1004 3 Let Ident	i Gg 2. Stock	- 1)	05 01 10 05/01/11 05/01/11
3	PK	Identify & Stock: Qty Part Number	Description	Batch		

Close W/O Inspect Level 21

DC